

RESOLUTION #19-0219-08

Authorize Additional Expenditures for Emergency Repairs to Road Department Vehicle

WHEREAS, the Liberty Township Parks and Road Services Department Road Department truck was in need of emergency repairs due to an issue which rendered the vehicle inoperable, and

WHEREAS, the Board of Trustees approved repairs in the amount of \$2,972.49 with Resolution #19-0204-13, and

WHEREAS, it has been determined by the service vendor that additional repairs are needed to make the vehicle operable.

NOW, THEREFORE BE IT RESOLVED BY THE BOARD OF TRUSTEES OF LIBERTY TOWNSHIP, DELAWARE COUNTY, OHIO to authorize an additional expenditure from Road funds for the emergency repair of the Road Department vehicle in an amount not to exceed \$4,916.08 payable to Rush Truck Center, 3950 Parkwest Drive, Columbus, OH 43228; this brings the total cost of the repair to \$7,888.57.

Motion made by Leneghan and seconded by Eichhorn.

Vote: yes Mrs. Eichhorn yes Mr. Gemperline yes Mrs. Leneghan

This Resolution shall be in force and become effective immediately upon its execution.

Feb. 19, 2019

Date

Melanie Leneghan
Melanie Leneghan, Trustee

Mike Gemperline
Mike Gemperline, Trustee

CERTIFIED BY:

Nancy Denuette
Nancy Denuette, Fiscal Officer

Shyra Eichhorn
Shyra Eichhorn, Trustee

Currency: USD

Unit No: 4

Liberty Twns Trustees

VIN: 1HTWDAAR15J052548
Model: 7400 SFA 4X2
Engine: DT466 HT 245HP/2400 GOV
Make: International
Delivered: 8/23/2004
In Service: 14 Years 5 Months
Mileage: 0 Eng Hrs: 0

Recall/AFC: No


Contact Name:
Position:
Phone:
E-Mail:
PO Number:

Operation (All Sections)	Labor Cost	Parts Cost	Core Charge	Total Cost
Tow / Vehicle Recovery - Fixed Cost	\$0.00	\$0.00	\$0.00	\$350.00
ELectronic transmission diagnostics	\$298.00	\$0.00	\$0.00	\$298.00
Computer Hook Up (PRINT / CLEAR CODES, PASSWORD CHANGE, HP INCREASE, ETC..) - Fixed Cost	\$0.00	\$0.00	\$0.00	\$50.00
Disable Vehicle Tow-In, Allowance	\$89.40	\$0.00	\$0.00	\$89.40
Repair wiring harness to transmission (20) TIES (2) TAPE, COROPLAST ADHESIVE POLYESTER (20) SLEEVE, HEAT SHRINK (20) TERMINAL, BUTT SPLICE UNINSULATED 22-18 GAUGE (2) BDT23410FT (4) BDT234112FT (2) BDT23412FT (2) BDT23413FT (2) BDT23414FT (20) TERMINAL, CABLE	\$521.50	\$628.58	\$0.00	\$1,150.08
Service air system (1) AIR BRAKE ANTIFREEZE	\$149.00	\$15.74	\$0.00	\$164.74
Air Dryer, Replace (1) FLEETRITE AIR DRYER; REPLACEMENT TYPE: BENDIX AD-9; TYPE: NEW; CORE: NO	\$149.00	\$230.00	\$0.00	\$379.00
Intake heater diagnostics	\$149.00	\$0.00	\$0.00	\$149.00
Electronic Control Module (ECM OR ECM/IDM), Replace (1) MODULE, REMANUFACTURED ELECTRONIC CONTROL I313	\$715.20	\$3,400.00	\$0.00	\$4,115.20
Abs System, Diagnostics (ELECTRONIC)	\$149.00	\$0.00	\$0.00	\$149.00
Alternator, R & R Or Replace (1) BELT, FAN RIBBED "V" 8 PACKAGE 2348 MM (1) ALTERNATOR PAD MOUNTING	\$149.00	\$499.90	\$0.00	\$648.90
Diag, Roadtest, Snapshot, Graph Analysis	\$89.40	\$0.00	\$0.00	\$89.40

Notes: [1/29/2019 1:11 PM] - Dealer: Customer states unit will not go into gear
Found Corroded wires at harness

Parts: \$4,774.22
Core: \$0.00
Labor: \$2,458.50
Other Items: \$400.00
Shop: \$245.85
Tax: \$0.00


Haz. Waste:	\$10.00
TOTAL:	\$7,888.57

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED BY: 

DATE: 2/19/19

Repair Management
BY NAVISTAR

RUSH TRK CTR OF S OH
3950 PARKWEST DR - COLUMBUS, OH 43228
Phone: (1) 614-5414610 - Fax: (1) 614-5414673
Estimate Number: 2338494 - RO Number: 20547974
Service Writer: Tim Zatek - Date: 1/29/2019 1:11 PM (C)



Currency: USD

Unit No: 4

Liberty Twns Trustees

VIN: 1HTWDAAR15J052548
Model: 7400 SFA 4X2
Engine: DT466 HT 245HP/2400 GOV
Make: International
Delivered: 8/23/2004
In Service: 14 Years 5 Months
Mileage: 0 Eng Hrs: 0

Recall/AFC: No

Contact Name:
Position:
Phone:
E-Mail:
PO Number:

Operation (All Sections)	Labor Cost	Parts Cost	Core Charge	Total Cost
Tow / Vehicle Recovery - Fixed Cost	\$0.00	\$0.00	\$0.00	\$350.00
Electronic transmission diagnostics	\$298.00	\$0.00	\$0.00	\$298.00
Computer Hook Up (PRINT / CLEAR CODES, PASSWORD CHANGE, HP INCREASE, ETC..) - Fixed Cost	\$0.00	\$0.00	\$0.00	\$50.00
Disable Vehicle Tow-In, Allowance	\$89.40	\$0.00	\$0.00	\$89.40
Repair wiring harness to transmission (20) TIES (2) TAPE, COROPLAST ADHESIVE POLYESTER (20) SLEEVE, HEAT SHRINK (20) TERMINAL, BUTT SPLICE UNINSULATED 22-18 GAUGE (2) BDT23410FT (4) BDT234112FT (2) BDT23412FT (2) BDT23413FT (2) BDT23414FT (20) TERMINAL, CABLE	\$521.50	\$628.58	\$0.00	\$1,150.08
Service air system (1) AIR BRAKE ANTIFREEZE	\$149.00	\$15.74	\$0.00	\$164.74
Air Dryer, Replace (1) FLEETRITE AIR DRYER; REPLACEMENT TYPE: BENDIX AD-9; TYPE: NEW; CORE: NO	\$149.00	\$230.00	\$0.00	\$379.00
Intake heater diagnostics	\$149.00	\$0.00	\$0.00	\$149.00
Electronic Control Module (ECM OR ECM/IDM), Replace (1) MODULE, REMANUFACTURED ELECTRONIC CONTROL I313	\$715.20	\$3,400.00	\$0.00	\$4,115.20
Abs System, Diagnostics (ELECTRONIC)	\$149.00	\$0.00	\$0.00	\$149.00
Alternator, R & R Or Replace (1) BELT, FAN RIBBED "V" 8 PACKAGE 2348 MM (1) ALTERNATOR PAD MOUNTING	\$149.00	\$499.90	\$0.00	\$648.90
Diag, Roadtest, Snapshot, Graph Analysis	\$89.40	\$0.00	\$0.00	\$89.40

Notes: [1/29/2019 1:11 PM] - Dealer: Customer states unit will not go into gear
Found Corroded wires at harness

Parts: \$4,774.22
Core: \$0.00
Labor: \$2,458.50
Other Items: \$400.00
Shop: \$245.85
Tax: \$0.00

Estimate #2338494

Parts Card

Customer: Liberty Twns Trustees
Vehicle: 7400 SFA 4X2

Mileage: 0
VIN: 1HTWDAAR15J052548

RO: 20547974
Date: 1/29/2019

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Electronic transmission diagnostics

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		
Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Disable Vehicle Tow-In, Allowance

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Repair wiring harness to transmission

Qty	Part Number	Part Name	Price (ea)	Total
20	38951	TIES	\$0.09	\$1.80
2	2509328C1	TAPE, COROPLAST ADHESIVE POLYESTER	\$20.90	\$41.80
20	2644000R1	SLEEVE, HEAT SHRINK	\$4.74	\$94.80
20	3517503C1	TERMINAL, BUTT SPLICE UNINSULATED 22-18 GAUGE	\$15.74	\$314.80
2	BDT23410FT	BDT23410FT	\$0.19	\$0.38
4	BDT234112FT	BDT234112FT	\$0.19	\$0.76
2	BDT23412FT	BDT23412FT	\$0.19	\$0.38
2	BDT23413FT	BDT23413FT	\$0.19	\$0.38
2	BDT23414FT	BDT23414FT	\$0.14	\$0.28
20	3508927C1	TERMINAL, CABLE	\$8.66	\$173.20

Service air system

Qty	Part Number	Part Name	Price (ea)	Total
1	5601	AIR BRAKE ANTIFREEZE	\$15.74	\$15.74

Air Dryer, Replace

Qty	Part Number	Part Name	Price (ea)	Total
1	FLTAD5225	FLEETRITE AIR DRYER; REPLACEMENT TYPE: BENDIX AD-9; TYPE: NEW; CORE: NO	\$230.00	\$230.00

Intake heater diagnostics

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Electronic Control Module (ECM OR ECM/IDM), Replace

Qty	Part Number	Part Name	Price (ea)	Total
1	5011238R1	MODULE, REMANUFACTURED ELECTRONIC CONTROL I313	\$3,400.00	\$3,400.00

Abs System, Diagnostics (ELECTRONIC)

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Alternator, R & R Or Replace

Qty	Part Number	Part Name	Price (ea)	Total
1	1842461C1	BELT, FAN RIBBED "V" 8 PACKAGE 2348 MM	\$64.90	\$64.90
1	8600066	ALTERNATOR PAD MOUNTING	\$435.00	\$435.00

Diag, Roadtest, Snapshot, Graph Analysis

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		